

Water Sampling Log

Name of Building: Alpha School
 Building Owner: Alpha Board of Education

Date Collected: 13-May-16
 Sample Collected by: R.C. Ellis

Sample No.	Sample Type	Type of Outlet	Manufacturer	Location	Time	Results (mg/L)	
						Cu	Pb
AS-051316-01	1st	Faucet	American Std.	Business Administrator Office sink	06:04	0.082	0.010
AS-051316-02	1st	Faucet	-	Main Office sink	06:06	0.12	0.0040
AS-051316-03	1st	Bubbler	American Std.	Rm 11 sink	06:08	0.24	0.045
AS-051316-04	1st	Bubbler	Halsey Taylor	Hallway - next to Main Office (right) - left permanently out of service	06:09	0.13	0.0031
AS-051316-05	1st	Bubbler	Halsey Taylor	Hallway - next to Rm A (left)	06:11	0.12	ND
AS-051316-06	1st	Bubbler	Halsey Taylor	Hallway - next to Rm A (right)	06:12	0.15	0.0037
AS-051316-07	1st	Bubbler	Standard	Hallway - opposite Nurse's Office	06:15	0.096	0.0045
AS-051316-08	1st	Faucet	-	Nurse's Office sink	06:16	0.18	0.0031
AS-051316-09	1st	Bubbler	-	Nurse's Office sink	06:16	0.17	0.0038
AS-051316-10	1st	Bubbler	-	Rm 6 sink	06:17	0.12	0.0031
AS-051316-11	1st	Bubbler	-	Rm 5 sink	06:18	0.15	0.0063
AS-051316-12	1st	Chiller	Elkay	Cafeteria Dining area	06:19	0.27	ND
AS-051316-13	1st	Faucet	-	Kitchen sink - next to entrance & register	06:20	0.22	0.0069
AS-051316-14	1st	Faucet	-	Kitchen sink - next to refrigerator	06:20	0.16	0.014
AS-051316-15	1st	Faucet	-	Janitor Closet sink	06:22	0.15	0.0024
AS-051316-16	1st	Bubbler	-	Rm 4 sink	06:23	0.13	0.0064
AS-051316-17	1st	Bubbler	Standard	Multi-Purpose Rm	06:24	0.12	0.0041
AS-051316-18	1st	Bubbler	Standard	Hallway - opposite Multi-Purpose Rm left entrance	06:25	0.14	ND
AS-051316-19	1st	Bubbler	-	Rm 3 sink	06:26	0.21	0.020
AS-051316-20	1st	Bubbler	-	Rm 2 sink	06:27	0.13	ND

Sample Type: **1st:** First Draw sample collected after water has been unused at least 8 hours but not more than 18 hours.

FL: Water flushed through tap for at least 2 minutes

ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0050 for Copper and 0.0020 mg/L for Lead.

Water Sampling Log

Name of Building: Alpha School
 Building Owner: Alpha Board of Education

Date Collected: 13-May-16
 Sample Collected by: R.C. Ellis

Sample No.	Sample Type	Type of Outlet	Manufacturer	Location	Time	Results (mg/L)	
						Cu	Pb
AS-051316-21	1st	Bubbler	-	Rm 1 sink (low flow)	06:29	0.24	0.012
AS-051316-22	1st	Faucet	-	Rm 4 sink	06:34	0.17	0.0052
AS-051316-23	1st	Bubbler	Standard	Hallway opposite Rm B	06:37	0.12	ND
AS-051316-24	1st	Bubbler	-	Rm 17 sink	06:38	0.20	0.0095
AS-051316-25	1st	Faucet	-	Faculty Room sink	06:39	0.18	0.0036
AS-051316-26	1st	Bubbler	-	Special Services Rm (Library Work Rm) sink	06:41	0.21	0.029
AS-051316-27	1st	Faucet	-	Special Services Rm (Library Work Rm) sink	06:42	0.35	0.051
AS-051316-28	1st	Faucet	-	Rm 18 sink	06:44	0.22	0.018
AS-051316-29	1st	Bubbler	Standard	Hallway - next to right Library door	06:46	0.18	ND
AS-051316-30	1st	Bubbler	-	Rm 19 sink	06:48	0.26	0.025
AS-051316-31	1st	Faucet	-	Rm 19 sink	06:49	0.12	0.019
AS-051316-32	1st	Faucet	-	Rm 20 sink (bubbler not working)	06:51	0.41	0.069

Sample Type: **1st:** First Draw sample collected after water has been unused at least 8 hours but not more than 18 hours.
FL: Water flushed through tap for at least 2 minutes
ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0050 for Copper and 0.0020 mg/L for Lead.